

Swan soundbar

- No boot issue



ALT Co., Ltd.


Issued Date 2021.08.11

Ver.1.0


Issued by SH, SON



- Symptom
 - No booting after power on
 - in no boot status, power consumption is 1.9~2W
 - unscrew a half turn near the eMMC screw
 - Start the booting
 - Video clip
 - https://www.dropbox.com/s/tbiauamcmdkonge/20210802_185409.mp4?dl=0
- ALT reviewed
 - Visual inspection : Normal
 - System review on board level : Normal
 - BGA X-ray inspection : Normal
- ALT is suspected that Physical damage such as PCB cracks or BGA cracks.
- FII should be analyze the defect.

VS550




eMMC








VS550




eMMC








VS550



eMMC





- End of Documents