

SWAN Rub and Buzz Improvement – FXN side

SH Son

First Update

2020.12.14

Last Update

2020.00.00



The elec cap need to applied bonding.

: This is make 350Hz band Rub and Buzz noise.

- The elecap is not completely tight to PCB.
- due to Sound vibration is shaking the electric cap.

Suggestion Solution

: Apply silicon between PCB and all of Elecap (4 point)




Heat spreader is also make Rub and Buzz noise.

: Amp PCBA and Heat spreader amp bottom is to create noise.

Suggestion Solution

: Cutting area adding and expanding



Add Cutting area : 4 point

**Expanding cutting area :
3 point, +1 pi**

