

Swan_soundbar_DVT2_Assembly review v0.1






ALT Co., Ltd.

Issued Date 2021.05.11

Ver.1.0



Issued by SH, SON

- PCB/FFC contamination



NG



- AMP Bottom heat spreader screws are not fastened.



- ALT Comment
 - If inner structure is not fastened, can be make vibration noise
 - Please update Fii SOP as a CTQ

NG

- Top Gasket is missing





NG

- ALT Comment
 - Top gasket is critical to quality (CTQ) to prevent air leakage.
 - Please update Fii SOP as a CTQ




- Inner Gasket is missing



- ALT Comment
 - Top gasket is critical to quality (CTQ) to prevent air leakage.
 - Please update Fii SOP as a CTQ

NG

- Screw is missing



- ALT Comment
 - If inner structure is not fastened, can be make vibration noise
 - Please update Fii SOP as a CTQ

NG

- Label attachment NG



- ALT Comment
 - to be updated VI spec as a failure example
 - Please update Fii SOP

NG

- End of Documents