

Gasket position difference between KC report (OT-210-RET-001) and
"EMI test status_Rev1.5.pdf"


1. Top gasket

KC report (OT-210-RET-001), figure 2 on page 7

조치내용 - 2. 제품 내부에 가스켓 적용




EMI test status_Rev1.5.pdf, page 18



2. Gasket on main board


KC report (OT-210-RET-001), figure 2 on page 7

조치내용 - 6. 메인보드에 가스켓 적용



EMI test status_Rev1.5.pdf, page 17/18

Add Gaskets on main BD



Add Gaskets on main BD

