

Eagle

2023.11 Mass production inspection

SH Son

Model Name: BFX-AT100

Document Version: ALT_STB_MP_CSMTINS_001

Issued Date: 2023.11.29



ALT

All Life Technology Co., Ltd



Confidential

Document History

Version	Editor	Date	Updates
001	SH Son (Seunghwan Son)	2023.11.29	initial version

- SKB incoming inspection
 - Inspection lot : BFX-AT100 35k delivered on 2023.11
 - Sampling size : AQL 0.15 (1000pcs)
 - Date : 2023.11.16 ~ 2023.11.22
 - Location : [SK networks warehouse](#), Anseong, Korea.
- Overall inspection result
 - Conditional Pass
- Defect Total
 - Critical
 - N/A
 - Major
 - Stain of Top housing rear side * 25%
 - Minor
 - HDMI cable cosmetic issue * 1pcs

Definition*

- Critical : The **defect related to product functions**
- Major : The defect is no effect on the product functions. But **visually defect**. (i.g cosmetic damaged.)
- Minor : The defect is no effect on the product functions, no visually defect. But **need improvement**

Confidential

- Issue grade : Major

- Defect unit Q'ty : 25pcs / 100pcs

- SN

- 2149688001202301295521~2149688001202301295530 / 2149688001202301295561~2149688001202301295570
- 2149688001202301295741~2149688001202301295750 / 2149688001202301298511~2149688001202301298520
- 2149688001202301309931~2149688001202301309940 / 2149688001202301301911~2149688001202301301920
- 2149688001202301307711~2149688001202301307720 / 2149688001202301309991~2149688001202301310000
- 2149688001202301309931~2149688001202301309940 / 2149688001202301309911~2149688001202301309920

- Symptom

- Stain of Top housing rear side
 - This stain can't be erased
- See the next page for more pictures

- ALT initial review


- Visual check -> NG
- ALT got the one-time waiver this Stain from customer quality manager.



- Action item

- FXN should be submit 8D report
 - Sorting before production..
 - Fine the root cause.
 - Provide the preventive action

Stain of Top housing rear side



Confidential

- Issue grade : Minor
 - Defect unit Q'ty : 1pcs / 1000pcs
- Symptom
 - HDMI cable cosmetic issue
- ALT initial review
 - Visual Check -> NG
 - Replace normal HDMI Cable
- Action item
 - FXN should be submit 8D report
 - For short term solution
 - The root cause.
 - Provide the preventive action



Thank you.

ALT
All Life Technology Co., Ltd

Confidential