

Eagle

2025.03 Mass production inspection

SH Son

Model Name: BFX-AT100

Document Version: ALT_STB_MP_CSMTINS_001

Issued Date: 2025.03.28



ALT

All Life Technology Co., Ltd



Confidential

Document History

Version	Editor	Date	Updates
001	SH Son (Seunghwan Son)	2025.03.25	initial version
002	SH Son (Seunghwan Son)	2025.03.28	update

- SKB incoming inspection
 - Inspection lot : BFX-AT100 30k delivered on 2025.03
 - Sampling size : AQL 0.15 (1000pcs)
 - Date : 2025.03.12 ~ 2025.03.18
 - Location : [SK networks warehouse](#), Anseong, Korea.
- Overall inspection result
 - Pass
- Defect Total
 - Critical
 - N/A
 - Major
 - N/A
 - Minor
 - HDMI cable function NG * 2pcs
 - HDMI cable cosmetic NG * 1pcs


Definition*

- Critical : The **defect related to product functions**
- Major : The defect is no effect on the product functions. But **visually defect**. (i.g cosmetic damaged.)
- Minor : The defect is no effect on the product functions, no visually defect. But **need improvement**

Confidential

- Issue grade : Minor
 - Defect unit Q'ty : 2pcs / 1000pcs
 - SN : N/A
- Symptom
 - HDMI cable function NG – No signal on the TV
- ALT initial review
 - Visual Check -> No found abnormal
 - Function check -> Connect to TV : NG
- Action item
 - FXN should be submit 8D report
 - For short term solution
 - The root cause.
 - Provide the preventive action

- Issue grade : Minor
 - Defect unit Q'ty : 1pcs / 1000pcs
 - SN : N/A
- Symptom
 - HDMI cosmetic NG
- ALT initial review
 - Looks like a glue, replace the new HDMI cable
- Action item
 - FXN should be submit 8D report
 - For short term solution
 - The root cause.
 - Provide the preventive action



Thank you.

ALT
All Life Technology Co., Ltd

Confidential