


The experiment of changing the capacitance of C338


The capacitance we used in SKB Eagle board now

- C338: CC0402KRX5R7BB104 (0.1u 16V 0402)



Change the capacitance value to 1uF/50V

- C338: GRM155R61H105KE05D (1u 50V 0402)



We can find that the overshoot still over TI (20V tolerance) spec.