

Eagle

LED Defect

SH Son

Model Name: BFX-AT100

Document Version: ALT_STB_MP_CSMTINS_001

Issued Date: 2022.03.25



ALT

All Life Technology Co., Ltd



Confidential

- SKB incoming inspection
 - Inspection lot : BFX-AT100 40k delivered on Mar
 - Sampling size : AQL 0.15 (1000pcs)
 - Date : 2022.3.22 ~ 2022.3.25
 - Location : [SK networks warehouse](#), Anseong, Korea.
- Overall inspection result
 - TBD
- Defect Total
 - Critical
 - TBD
 - Major
 - LED defect * 2 pcs
 - Minor
 - TBD

- Issue grade : Major

- Defect unit Q'ty : 2pcs / 500pcs
- Defect rate : 0.4%

SN	MAC
21496870012022011126732	38:d5:7a:d8:e8:09
21496870012022011126654	38:d5:7a:d8:e6:c9



- Action item

- Factory should be submit 8D report
 - Find the root cause
 - Provide the preventive action

- Note.

- Led was already applied long term solution. But LED defect (color change, i.g White -> Pink) is recurrence

Thank you.

ALT
All Life Technology Co., Ltd

Confidential