



International Certification Corp. (全球檢測股份有限公司)

Tel : 886-3-271-8666

Fax : 886-3-318-0155

No.3-1, Lane 6, Wen San 3rd St., Kwei Shan Hsiang, Tao Yuan Hsein 333, Taiwan (R.O.C.)

IEC/EN 61000-4-11 DIP TEST RECORD

Applicant:	鴻齡	ICC No:	
EUT:		Model:	SBB OTT
Test mode:	Mode1 , 2	Sample No:	
Operating Conditions of EUT:		Mode1:IR remote control ,Run LAN Ping test , Play VLC MP4 , “ADB” test program recording Mode2: BT remote control with earphone ,Run LAN Ping test , Play VLC MP4 , “ADB” test program recording	
Input Voltage:	AC <u>230</u> V / <u>50</u> Hz or DC <u> </u> V	Approved by	

Test Site: <u>EX01-WS</u>													
Temperature / Humidity: <u>19</u> °C / <u>58</u> % Atmospheric Pressure: <u>103</u> kPa (86kPa to 106kPa)													
Tested by: <u>JN Chen</u>										Date: <u>2019</u> (yy) <u>03</u> (mm) <u>06</u> (dd)			
Mode1 , 2													
☒ IEC 61000-4-11 ☐ EN 61000-4-11 ☒ EN 55024 ☐ EN 301489 ☐ _____							☐ IEC 61000-4-11 ☐ EN 61000-4-11 ☐ EN 55024 ☐ EN 301489 ☐ _____						
Test Voltage	Item	Reduction	Residual	Voltage Cycle	Observation	Performance Criteria	Test Voltage	Item	Reduction	Residual	Voltage Cycle	Observation	Performance Criteria
		Voltage (%)							Voltage (%)				
240V/50Hz	Voltage Dip	>95		0.5	Note 1	A							
240V/50Hz	Voltage Dip	30		25	Note 1	A							
240V/50Hz	Voltage Interruption	>95		250	Note 2	C							
230V/50Hz	Voltage Dip	>95		0.5	Note 1	A							
230V/50Hz	Voltage Dip	30		25	Note 1	A							
230V/50Hz	Voltage Interruption	>95		250	Note 2	C							
100V/50Hz	Voltage Dip	>95		0.5	Note 1	A							
100V/50Hz	Voltage Dip	30		25	Note 1	A							
100V/50Hz	Voltage Interruption	>95		250	Note 2	C							
☒ <u>EN 55024</u> Performance Criterion: <u>C</u>							☐ _____ Performance Criterion: _____						
Test Result : Note1 : There was no abnormal situation during the test compared with initial operation. Note2 : The EUT lost power during the test and must be recovered manually.													
According to : ☒ Standard ; ☐ Manufacturer													