

Eagle

ABS T4 Feedback

Model Name: BFX-AT100

Document Version: ALT_STB_MP_CSMTINS_001

Issued Date: 2023.01.17




ALT

All Life Technology Co., Ltd




Confidential

- Large gap between LED leans and Top case
 - It is same gap as T4 and T3
 - ALT is suggest that increase the light pipe size



T3 - Top view



T4 – Top view

Confidential

- Need to improve gas mark
 - T4 condition is not good



Confidential


- Remove the weld line
 - This area is “A” surface and more visible than before
 - T4 : no improvement



- LED leans
 - The light emitting surface is not uniform
 - Same as T3 and T4.
 - Due to different surfaces, reflect the light



LED on



LED off



Confidential

- Each side has looks like scratch.
 - Find the root cause, and improve T5 injection
 - T3 has also same.




Confidential

Injection date code

- Please update each injection date



Marked 21.5.00



Marked N/A

Confidential

Thank you.

ALT
All Life Technology Co., Ltd

Confidential