

HWQA & Project Update (1)

Sub BU	Product Line	Issue	Action	Status Signal	FCS Date	Impact
JBD ●	UA300 (K18X001T00) A400 RD: Jim HWQA: Jackson Huang	Logo/Printing Abrasion Test -Test Condition: Loading force: 1000g Test cycles: 2000 cycles for the abrasion by the 95% alcohol solvent. - H/W: V125. - S/W: 19.524.23. -Symptom: After the test, the Logo was wear disappeared.	Feedback this issue to RD: Jim, and he is studying the issue. Due : TBD	●	TBD	NA

