

Eagle

2023.06 Mass production inspection

SH Son

Model Name: BFX-AT100

Document Version: ALT_STB_MP_CSMTINS_001

Issued Date: 2023.06.13



ALT

All Life Technology Co., Ltd



Confidential

Document History

Version	Editor	Date	Updates
001	SH Son (Seunghwan Son)	2023.06.19	initial version

- SKB incoming inspection
 - Inspection lot : BFX-AT100 26k delivered on 2023.06
 - Sampling size : AQL 0.15 (1000pcs)
 - Date : 2023.06.12 ~ 2023.06.15
 - Location : [SK networks warehouse](#), Anseong, Korea.
- Overall inspection result
 - Conditional Pass
- Defect Total
 - Critical
 - Abnormal reboot after System hangup * 1pcs
 - Major
 - N/A
 - Minor
 - N/A

Definition*

- Critical : The **defect related to product functions**
- Major : The defect is no effect on the product functions. But **visually defect**. (i.g cosmetic damaged.)
- Minor : The defect is no effect on the product functions, no visually defect. But **need improvement**

Confidential

- Issue grade : Critical
 - Defect unit Q'ty : 1pcs / 1000pcs
 - SN : 2149688001202301146495
- Symptom
 - Normal operation for several minutes after power on
 - Abnormal reboot and System hangup
- ALT initial review
 - Check visual status -> No found abnormal
 - USB log is attached : Log.zip
- Action item
 - FXN should be submit 8D report
 - For short term solution
 - The root cause.
 - Provide the preventive action

Thank you.

ALT
All Life Technology Co., Ltd

Confidential